


ľľ

Axis sensor



#### Description

The K3A 3-axis sensor is designed for measuring force in three mutually perpendicular axes. This product group has a wide measurement ranges for the forces.

The K3A S3-Axis Force Sensors are developed for the following applications:

- 1. Robotics,
- 2. Medical technology,
- 3. Measurements in automation technology,
- 4. Mounting and Assembling of Parts in Production Lines,
- 5. 6-Axis Force/Torque Platforms consisting of 4x K3A Sensors,
- 6. Research and Testing.

The calibration document contains the individual calibration factors and crosstalk data of the sensor. The crosstalk optionally can be minimized by application af an additional error compensation matrix. The K3A sensors can be operated without additional compensation matrix.


During the application, please take care to ensure that the maximum bending moments are not exceeded. The lever arms are calculated from the sensor origin, which is in the center of the mounting surface (on the top surface).



ľľ

Axis sensor

#### **Dimensions**







Axis sensor

### **Technical Data**

Force sensor		
Туре	3-axis force sensor	
Force direction	Tension / Compression	
tated force Fx	100	kN
ated force Fy	100	kN
ated force Fz	200	kN
orce introduction	Inner thread	
imension 1	8xM20x2,5	
ensor Fastening	Inner thread	
imension 2	8xM20x2,5	
perating force	150	%FS
Material	Tool steel	
leight	150	mm
ength or Diameter	225	mm
orque limit	40	kNm
Bending moment limit	10	kNm
Precision		
	0,2%	
elative linearity error	0.2	%FS
<u> </u>		
emperature effect on zero signal	0.01	%FS/K
emperature effect on characteristic value	0.01	%RD/K
Relative creep	0.01	%FS
Connection Data		
Connection type	Connector	
lame of the connection	integrierter Rundsteckverbinder	
	UP13, 27-polig, male	
ccentricity and Crosstalk		
rosstalk from x to y at rated load	2	%FS
rosstalk from y to x at rated load	2	%FS
Crosstalk from z to x/y at rated load	1	%FS
Crosstalk from x/y to z at rated load	1	
emperature		
Rated temperature range f	-10 70	°C
Operating temperature range f	-10 85	°C
· · · · · · · · · · · · · · · · · · ·	.0 00	
Section Desc		
Electrical Data		NAL / FC
Rated output x-axis	1.5	mV/V / FS
Rated output y-axis	1.5	mV/V / FS
Rated output z-axis	0.8	mV/V / FS
tated output z-axis Eero signal Lated range of excitation voltage f	0.8 0.05 2.55	mV/V







Axis sensor

Operating range of excitation voltage f	1 10	V
Input resistance x-axis	700	Ohm
Output resistance x-axis	700	Ohm
Input resistance y-axis	700	Ohm
Output resistance y-axis	700	Ohm
Input resistance z-axis	1400	Ohm
Output resistance z-axis	1400	Ohm
Insulation resistance	5	GOhm

Abbreviation: RD: "Reading"; FS: "Full Scale"; The exact nominal sensitivity is indicated in the test report;







Axis sensor

### **Pin Configuration**

Channel	Symbol	Description	Wire colour	PIN
1 and 7	+Us	positive bridge supply	yellow	14
	-Us	negative bridge supply	green	13
	+Ud	positive bridge output	white	1
	-Ud	negative bridge output	brown	5
2 and 8	+Us	positive bridge supply	gray	15
	-Us	negative bridge supply	black	16
	+Ud	positive bridge output	red	7
	-Ud	negative bridge output	pink	6
3 and 9	+Us	positive bridge supply	brown-blue	23
	-Us	negative bridge supply	white-red	24
	+Ud	positive bridge output	brown-red	12
	-Ud	negative bridge output	white-pink	4
4 and 10	+Us	positive bridge supply	white-yellow	13
	-Us	negative bridge supply	yellow-brown	20
	+Ud	positive bridge output	brown-green	9
	-Ud	negative bridge output	white-green	3
5 and 11	+Us	positive bridge supply	white-gray	21
	-Us	negative bridge supply	white-blue	22
	+Ud	positive bridge output	gray-brown	10
	-Ud	negative bridge output	pink-brown	11
6 and 12	+Us	positive bridge supply	gray-pink	18
	-Us	negative bridge supply	purple	17
	+Ud	positive bridge output	red-blue	8
	-Ud	negative bridge output	blue	2
-	shield		transparent	

Shield: connected with sensor housing;

Plug connector 1: channel 1 - 6

Plug connector 2: channel 7 - 12





#### Axis sensor


### accessories

	Description	Description
22	GSV-8DS	8-channel amplifier with USB port, analog output, UART interface. Other versions GSV-8AS CAN with Canbus and GSV-8AS EC with EtherCAT fieldbus.
Q	Connection cable UP13/27p/f/90°-D- Sub44HD/m	Connection cable for connecting the K6D sensor to an 8-channel measuring amplifier GSV-8DS SubD44HD
.otl.,,,,,	Calibration Certificate kn/200/5/K3D	Factory calibration certificate for force from 21 kN to 200 kN in accordance with DIN EN ISO / IEC 17025 for test materials monitoring according to DIN ISO 9001: 2008 with 5 load levels and 3 series of measurements.
odl <sub>all</sub>	Calibration Certificate kn/1000/5/K3D	Factory calibration certificate for force from 201 kN to 1000 MN in accordance with DIN EN ISO / IEC 17025 for test materials monitoring according to DIN ISO 9001: 2008 with 5 load levels and 3 series of measurements.



ľ

Axis sensor



#### Description

The K3A 3-axis sensor is designed for measuring force in three mutually perpendicular axes. This product group has a wide measurement ranges for the forces.

The K3A S3-Axis Force Sensors are developed for the following applications:

- 1. Robotics.
- 2. Medical technology,
- 3. Measurements in automation technology,
- 4. Mounting and Assembling of Parts in Production Lines,
- 5. 6-Axis Force/Torque Platforms consisting of 4x K3A Sensors,
- 6. Research and Testing.

The calibration document contains the individual calibration factors and crosstalk data of the sensor. The crosstalk optionally can be minimized by application af an additional error compensation matrix. The K3A sensors can be operated without additional compensation matrix.


During the application, please take care to ensure that the maximum bending moments are not exceeded. The lever arms are calculated from the sensor origin, which is in the center of the mounting surface (on the top surface).



ľl

Axis sensor

#### **Dimensions**







#### Axis sensor

### **Technical Data**

Force sensor		
Туре	3-axis force sensor	
Force direction	Tension / Compression	
Rated force Fx	200	kN
Rated force Fy	200	kN
Rated force Fz	400	kN
Force introduction	Inner thread	
Dimension 1	8xM20x2,5	
Sensor Fastening	Inner thread	
Dimension 2	8xM20x2,5	
Operating force	150	%FS
Material	Tool steel	
leight	150	mm
ength or Diameter	225	mm
Forque limit	60	kNm
Bending moment limit	20	kNm
Precision		
Accuracy class	0,2%	
Relative linearity error	0.2	%FS
emperature effect on zero signal	0.01	%FS/K
Emperature effect on characteristic value	0.01	%RD/K
Relative creep	0.01	%FS
Connection Data Connection type	Connector	
Name of the connection	integrierter Rundsteckverbinder	
value of the connection	UP13, 27-polig, male	
ccentricity and Crosstalk		
Crosstalk from x to y at rated load	2	%FS
Crosstalk from y to x at rated load	2	%FS
Crosstalk from z to x/y at rated load	1	%FS
Crosstalk from x/y to z at rated load	1	
Temperature		
Rated temperature range f	-10 70	°C
Operating temperature range f	-10 85	°C
Teached Date		
Electrical Data		
Rated output x-axis	1.5	mV/V / FS
Rated output y-axis	1.5	mV/V / FS
Rated output z-axis	0.8	mV/V / FS
Zero signal	0.05	mV/V
Rated range of excitation voltage f	2.5 5	V







#### Axis sensor

Operating range of excitation voltage f	1 10	V
Input resistance x-axis	700	Ohm
Output resistance x-axis	700	Ohm
Input resistance y-axis	700	Ohm
Output resistance y-axis	700	Ohm
Input resistance z-axis	1400	Ohm
Output resistance z-axis	1400	Ohm
Insulation resistance	5	GOhm

Abbreviation: RD: "Reading"; FS: "Full Scale"; The exact nominal sensitivity is indicated in the test report;







Axis sensor

### **Pin Configuration**

Channel	Symbol	Description	Wire colour	PIN
1 and 7	+Us	positive bridge supply	yellow	14
	-Us	negative bridge supply	green	13
	+Ud	positive bridge output	white	1
	-Ud	negative bridge output	brown	5
2 and 8	+Us	positive bridge supply	gray	15
	-Us	negative bridge supply	black	16
	+Ud	positive bridge output	red	7
	-Ud	negative bridge output	pink	6
3 and 9	+Us	positive bridge supply	brown-blue	23
	-Us	negative bridge supply	white-red	24
	+Ud	positive bridge output	brown-red	12
	-Ud	negative bridge output	white-pink	4
4 and 10	+Us	positive bridge supply	white-yellow	13
	-Us	negative bridge supply	yellow-brown	20
	+Ud	positive bridge output	brown-green	9
	-Ud	negative bridge output	white-green	3
5 and 11	+Us	positive bridge supply	white-gray	21
	-Us	negative bridge supply	white-blue	22
	+Ud	positive bridge output	gray-brown	10
	-Ud	negative bridge output	pink-brown	11
6 and 12	+Us	positive bridge supply	gray-pink	18
	-Us	negative bridge supply	purple	17
	+Ud	positive bridge output	red-blue	8
	-Ud	negative bridge output	blue	2
-	shield		transparent	

Shield: connected with sensor housing;

Plug connector 1: channel 1 - 6

Plug connector 2: channel 7 - 12





#### Axis sensor

#### accessories

	Description	Description
88	GSV-8DS	8-channel amplifier with USB port, analog output, UART interface. Other versions GSV-8AS CAN with Canbus and GSV-8AS EC with EtherCAT fieldbus.
Q	Connection cable UP13/27p/f/90°-D- Sub44HD/m	Connection cable for connecting the K6D sensor to an 8-channel measuring amplifier GSV-8DS SubD44HD
الندروب	Calibration Certificate kn/200/5/K3D	Factory calibration certificate for force from 21 kN to 200 kN in accordance with DIN EN ISO / IEC 17025 for test materials monitoring according to DIN ISO 9001: 2008 with 5 load levels and 3 series of measurements.
ورواله	Calibration Certificate kn/1000/5/K3D	Factory calibration certificate for force from 201 kN to 1000 MN in accordance with DIN EN ISO / IEC 17025 for test materials monitoring according to DIN ISO 9001: 2008 with 5 load levels and 3 series of measurements.